#### **IGNITION FURNACE TEST INSTRUCTIONS**

The following samples have been forwarded to your laboratory:

Material I-IGCF-(N) (Five samples)

Material I-IGMF-(N) and II-IGMF-(N) (Two pre-mixed samples)

Asphalt Cement I-IGAC-(N) (One sample)

## A) Ignition Furnace: Reference Procedure ASTM D6307

- 1) While furnace is at room temperature calibrate the furnace balance as described in the furnace manual provided by the manufacturer.
- 2) Set the combustion temperature of 540°C (deemed appropriate for this type of sample) or as indicated for Irradiation type furnace.
- 3) Set the start time (Auto Timer) so that the furnace is at the specified run temperature (see 2) above) for at least 60 minutes before starting the burn of the first sample of the day.
- 4) Set the furnace endpoint to 0.01% of the sample mass (D6307)

## **B)** Sample Preparation

### Correction Factor (I-IGCF-(N)) Samples:

- 1) Five sample bags containing approximately 1500g of mixed aggregates and one sample of asphalt cement are supplied
- 2) Aggregates are to be dried prior to mixing.
- A clean mixing bowl will be buttered by mixing a separate sample of HMA (not supplied). The bowl will be scraped clean of this buttering mix prior to mixing the five samples supplied.
- 4) Mixing temperature for the correction factor samples is 150°C.
- 5) Weigh and record the dried aggregate sample.
- 6) Based on this weight add sufficient asphalt cement (supplied) to produce a mix containing **5.00%**, **I-IGAC-(N)** (based on total mix).
- 7) Mix the sample as indicated in D-6926
- 8) Transfer the mixed sample to a metal tray, spread it out, cover with metal foil and allow it to cool to ambient temperature.
- 9) Sample is now ready for testing.
- 10) Five samples are provided. Calibration Factor shall be determined from 3 of the 5 samples according to D6307.

# Pre-mixed I-IGMF and II-IGMF-(N) Samples:

1) Sample bags containing approximately 1500g of **I-IGMF-(N)** and **II-IGMF-(N)** are supplied and are ready for testing. Determination of moisture content is not required.

## C) Ignition Furnace Run:

- Weigh the lid, sample tray, catch pan and retaining bracket on the laboratory balance (TABLE 1 – for I-IGCF-(N) (Correction Factor) samples and TABLE 3 – for I and II-IGMF-(N) (HMA) samples)
- 2) Preheat the sample to be tested to 110°C±5°C (i.e. sufficiently warm to handle). Do not heat for more than one hour.
- 3) Place catch pan under sample tray and spread sample evenly on the tray.
- 4) Place lid over sample tray and secure lid, tray and catch pan with the retaining bracket.

- 5) Weigh total assembly on the laboratory balance and record the mass to 0.1g (TABLE 1 for I-IGCF-(N) samples and TABLE 3 for I and II-IGMF-(N) samples)
- 6) Calculate sample mass (C in both TABLE 1 and TABLE 3)
- 7) Enter the sample mass C in the furnace data system.
- 8) Place the assembly in the preheated furnace and close the door.
- 9) Heat the sample at the specified temperature (540°C) until the difference between consecutive mass loss measurements does not exceed requirements for three one minute intervals.
- 10) Record sample mass after ignition (from data tape) (TABLE 1 F for I-IGCF-(N) samples and TABLE 3 F for I and II-IGMF-(N) samples).
- 11) Remove the assembly from the furnace and allow to cool to ambient temperature and weigh to the nearest 0.1g (TABLE 1 E for I-IGCF-(N) samples and TABLE 3 F for I and II-IGMF-(N) samples).
- 12) Record required data from tapes in TABLES 1 and 3 for I-IGCF-(N) and I and II-IGMF-(N) samples respectively.

NOTE: LABORATORIES SHOULD TAKE CAUTION REGARDING NEGATIVE CALIBRATION FACTORS. A LARGE NEGATIVE CALIBRATION FACTOR SUGGESTS THAT THE ASPHALT CEMENT HAS NOT BEEN COMPLETELY BURNED DURING THE IGNITION RUN.

# D) Ignited Aggregate Gradation

- 1) Carefully transfer the total residue after ignition to a weighing pan and weigh to the nearest 0.1g.
- 2) Proceed with the washed sieve gradation. Laboratories shall complete the attached work sheets (Tables 1-4) and submit copies of the output tapes from the ignition furnace runs.

Asphalt contents shall be expressed as mass percent of total mixture.

All test results shall be reported online and submitted by **January 5 2018**.

**NOTE for laboratories in British Columbia**: If your laboratory does not use the 16.0mm sieve, please do not enter zero in the online reporting form. Please cancel this sieve by clicking the box adjacent to the sieve in the reporting form.

An example of a completed report form is shown on page 3.

Hard copies of the report forms and work sheets (including Tables 1-4) must be submitted by **January 5 2018** by mail or courier to:

Nabil Kamel, M.A.Sc., P.Eng. CCIL Program Manager 3410 South Service Road, Suite 104 Burlington, Ontario, L7N 3T2

Tel: 289-337-8888: Fax: 289-337-8889: e-mail: <a href="mailto:nkamel@ccil.com">nkamel@ccil.com</a>

**DO NOT** send reports and worksheets by fax

2018 CCIL CORRELATION - EXAMPLE FORM BC, MB, NB, NL, NS and SK						
Testing Admin Information			your assigned C	CIL Lab No.:	BC99	
Lab Name (include Branch of	or Mobile #)	<b>Apex Const</b>	ruction			
E-mail Address	,	•	enstein@apex.xom			
Reported by (Contact Name	)		Frank Enste	ein		
Phone Number (Contact)			(999) 99	9-9999		
Tested by (Name(s))			I.P. Daly			
Results Reporting Date			January	5 2018		
D6307 IGNITION FURNACE	1	T	I			
Manufacturer:	Easy Bake	Model:	100 W	S/N:	123321	
Calibration Fact		- <b>IGCF) -</b> (Ente	er only the 3 s	amples used	d)	
	nple Number	Х	у	Z	Average	
• %A.C.		5.22	5.15	5.14	5.17	
% Passing Sieve, mm						
• 19.0		100.0	100.0	100.0	100.00	
16.0 BC labs only: Cancel si	eve? □	100.0	100.0	100.0	100.00	
• 13.2		97.6	98.4	98.1	98.03	
• 9.5		84.7	85.4	85.1	85.07	
• 4.75		63.6	63.4	63.8	63.60	
• 2.36		52.1 43.7	52.0 43.5	52.4	52.17	
• 1.18		33.7	33.5	43.6 33.7	43.60 33.63	
• 0.600 • 0.300		20.6	19.9	20.4	20.30	
• 0.300		8.3	8.0	8.2	8.17	
• 0.075		3.2	3.1	3.1	3.13	
3.3.3		<b>U.</b>	<u> </u>		0110	
Calibration Factor		0.22	0.15	0.14	0.17	
В	tuminous Mix	ι (I and II-IGM	F) Samples			
Sample N	umber		11	65	Average	
%A.C. Corrected			5.03	5.12	5.08	
% Passing Sieve, mm						
• 19.0		100.0	100.0	100.00		
• 16.0 BC labs only: Cancel si		100.0	100.0	100.00		
• 13.2		98.1	98.4	98.25		
• 9.5				85.4	85.25	
• 4.75	-	-	63.8	63.4	63.60	
• 2.36			52.4 43.6	52.0	52.20	
• 1.18				43.5	43.55	
• 0.600		33.7	33.5	33.60		
0.300		20.4	19.9	20.15		
• 0.150 • 0.075			8.2 3.1	8.0 3.1	8.10 3.10	
- 0.073			J. I	J. I	3.10	

**TABLE 1: In-House Prepared Calibration Factor Samples** 

General Information							
Compa	iny Name						
Technici	an's Name				Date		
		Sp	pecific Inform	nation			
				Calibr	ation Factor S	amples	
			Code No.	Code No.	Code No.	Code No.	Code No.
		La	aboratory Ba	lance	1		
А	Mass of sampl par	•					
В	Mass of sam catch pan,	nple tray, lid,					
C = (B - A)	Initial Mass	of Sample, g					
D	Mass of sample tray, lid, catch pan, sample after ignition, g						
E = (D - A) Final mass of sample after ignition, g							
Furnace Balance							
F	Final mass of ignition, g	sample after (data tape)					
G = (C - F)	Loss Fu	rnace, g					
H = (G/C) x 100	Loss Fur	rnace, %					
I	Loss Furnace	Correction, %					
J = (H – I)	Total Loss Furnace, % (Apparent AC)						
K	Total AC added, %						
L = (J - K)	= (J - K) Calibration Factor, %						
		Furnace	Temperature	Informatio	n		
Test tempera	ature shown on c	ontrols, °C					
Initial temper	ature from data	tape, °C					
Maximum ter	mperature form o	data tape, °C					
Final tempera	Final temperature from data tape, °C						

# TABLE 2: Gradation of In-House Prepared Calibration Factor Samples (After Ignition)

		Calibration Factor Samples				
		Code No.	Code No.	Code No.	Code No.	Code No.
Laboratory Balance	Initial Mass, g Final Mass,					
Furnace Balance	g Initial Mass, g Final Mass, g					
			AGGREGATE			
Dry mass befo	ore washing, g					
Dry mass afte	er washing, g	3				
			% Pa	ssing		
	16.0 mm					
	13.2 mm					
z	9.5 mm					
RADATION	4.75 mm					
D A .	2.36 mm					
	1.18 mm					
Ö	600 µm					
	300 μm					
	150 µm					
	75 μm					

Laboratory Name:		
·		
Date Tested:		

		G	eneral Inform		Gampioo		
Compa	iny Name						
Technici	an's Name				Date		
		Sı	pecific Inform	nation			
				Prepa	ared HMA Sa	mples	
			Code No.	Code No.	Code No.	Code No.	Code No.
		La	aboratory Ba	lance			
Α	Mass of sampl par	-					
В	Mass of san catch pan,	nple tray, lid,					
C = (B - A)	Initial Mass	of Sample, g					
D	Mass of sample tray, lid, catch pan, sample after ignition, g						
E = (D - A)	Final mass of sample after ignition, g						
			Furnace Bala	nce			
F	Final mass of ignition, g	sample after (data tape)					
G = (C - F)	Loss Furnace, g						
H = (G/C) x 100	Loss Fu	rnace, %					
I	Loss Furnace	Correction, %					
J = (H – I)	Total Loss (Appare	Furnace, % ent AC)					
CF*	Correction Factor, %						
L = (J – CF)	· Achhair Lamanr %						
		Furnace	Temperature	Information	1	T	
Test temperature shown on controls, °C							
Initial temper	ature from data	tape, °C					
	mperature form o	•					
Final tempera	Final temperature from data tape, °C						

* CF = Calibration factor as derived from the testing in TABLE 1	
Date Tested:	

TABLE 4: Gradation of Aggregates from Pre-mixed HMA Samples (After Ignition)

		Prepared HMA Samples				
		Code No.	Code No.	Code No.	Code No.	Code No.
<u> </u>						
Laboratory	Initial Mass, g					
Balance	Final Mass, g					
Furnace	Initial Mass, g					
Balance	Final Mass, g					
			AGGREGATE			
Dry mass befo	ore washing, g					
Dry mass aft	er washing, g					
			% Pa	ssing		
	16.0 mm					
	13.2 mm					
z	9.5 mm					
RADATION	4.75 mm					
D A _	2.36 mm					
	1.18 mm					
Ö	600 µm					
	300 µm					
	150 µm					
	75 μm					

Laboratory Name: Date	Tested:
-----------------------	---------